

**Fi Map (number of percent)**

		<u>All area Data change</u>									
TH(%)											
100	0%	0%	+ 1 %	+ 2 %	+ 3 %	+ 3 %	+ 2 %	+ 2 %	+ 2 %	0%	
80	0%	0%	+ 1 %	+ 2 %	+ 3 %	+ 3 %	+ 2 %	+ 2 %	+ 2 %	0%	
60	0%	0%	+ 1 %	+ 2 %	+ 3 %	+ 3 %	+ 2 %	+ 2 %	+ 2 %	0%	
40	0%	0%	+ 1 %	+ 2 %	+ 3 %	+ 3 %	+ 2 %	+ 2 %	+ 2 %	0%	
30	0%	0%	+ 1 %	+ 2 %	+ 3 %	+ 3 %	+ 2 %	+ 2 %	+ 2 %	0%	
20	0%	0%	+ 1 %	+ 2 %	+ 3 %	+ 3 %	+ 2 %	+ 2 %	+ 2 %	0%	
10	0%	0%	+ 1 %	+ 2 %	+ 3 %	+ 3 %	+ 2 %	+ 2 %	+ 2 %	0%	
0	0%	0%	+ 1 %	+ 2 %	+ 3 %	+ 3 %	+ 2 %	+ 2 %	+ 2 %	0%	Ne(r/Min)
	0	4000	5000	6000	8000	10000	12000	13500	15000	18000	